National Transportation Safety Board NTSB ID: DEN03LA016 Aircraft Registration Number: N7197C FACTUAL REPORT Occurrence Date: 11/17/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 80106 1030 **MST** Elbert Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

North American

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On November 17, 2002, about 1030 mountain standard time, a North American T-6G, N7197C, registered to and operated by the pilot, was substantially damaged when it nosed over during landing roll at Kelly Airpark, Elbert, Colorado. The commercial pilot and his passenger were not injured. Visual meteorological conditions prevailed, and no flight plan had been filed for the personal flight being conducted under Title 14 CFR Part 91. The flight originated at Elbert about 1015.

T-6G

The purpose of the flight was to take young children on their first airplane ride under the "Young Eagles" program. The pilot said that after a short flight, he made a normal three-point landing on runway 17, touching down at 75 to 80 mph. The wind was from 220 degrees at 14 knots. He used left rudder and tail wheel steering to keep the airplane from weathervaning into the wind. About 1,000 feet into the landing roll, the airplane veered sharply to the right. The pilot attempted to correct with opposite braking, but to no avail. The airplane went off the 36 foot wide runway about 40 mph onto soft ground and nosed over.

According to the pilot, when the airplane was retrieved, it was noted that the cable between the left rudder pedal pulley and the tail wheel was broken.

Airplane damage consisted of a crushed vertical stabilizer and rudder, left wing leading edge and tip, canopy, spinner and cowling, and a bent propeller. The engine, engine mounts, and firewall were also damaged.

Type of Aircraft

Airplane

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA016

Occurrence Date: 11/17/2002

7													
AVIATION		Occurrence Type: Accident											
Landing Facility/Approach Inf	ormation												
Airport Name Air				Airport Eleva	ation	Run	way Used	Runway Length		th	Runv	way Width	
Kelly Air Park			C015	7050 Ft	t. MSL	17	17 3800		0 2		24		
Runway Surface Type: Asphalt													
Runway Surface Condition: Dry													
Type Instrument Approach: NONE													
VFR Approach/Landing: Unknown													
Aircraft Information													
Aircraft Manufacturer				el/Series							Number		
North American			T-6	G 					4928	97			
Airworthiness Certificate(s): Norma	al												
Landing Gear Type: Retractable -	· Tailwheel												
Homebuilt Aircraft? No	Homebuilt Aircraft? No Number of Seats: 2				Certified Max Gross Wt. 556				0 LBS Numbe		er of Engines: 1		
9 11			Engine Manufacturer: Model/Series: 41-9754							Rated Power: 600 HP			
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection Time Sir			ince Last Inspection			Airfran	ne To	tal Time		
Annual			02/2002 75 Hou					ours	ours 6309 Hours				
- Emergency Locator Transmitter (E	ELT) Information												
ELT Installed? Yes	ELT Operat	ed? Yes	3		ELT	Aided i	n Locating Ac	cident S	Site? No)			
Owner/Operator Information													
Registered Aircraft Owner			Street	t Address On File									
Edward Huber			City							State	е	Zip Code 80106	
			Street	Address						100		00100	
Operator of Aircraft	Same as Reg'd Aircraft Owner												
Same as Reg'd Aircraft Owner				City						State	е	Zip Code	
Operator Does Business As: Operator Designator Code:													
- Type of U.S. Certificate(s) Held: N	lone												
Air Carrier Operating Certificate(s):													
Operating Certificate:				Operator	Certific	cate:							
Regulation Flight Conducted Under	: Part 91: Genera	al Aviati	on										
Type of Flight Operation Conducted	: Personal												
		FACTU	JAL REP	ORT - AVIAT	ION							Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA016

Occurrence Date: 11/17/2002

AVIATI	Occurrence Type: Accident										
First Pilot Information											
Name	City			Stat	te	Date of Birth	Age				
On File	On File			File	On File	60					
Sex: M Seat Occupied: Front Principal Profession: Unknown Certificate Number: On Fil										ber: On File	
Certificate(s): Flight Instructor; Commercial											
Airplane Rating(s): Multi-engine Land; Single-engine Land											
Rotorcraft/Glider/LTA:											
Instrument Rating(s): Airpl	ane										
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine											
Type Rating/Endorsement for	or Accident/In	cident Aircra	ft? No			Current Bie	nnial Flight	Review	v? 01/2	2002	
Medical Cert.: Class 2	Medica	al Cert. Status	S: Valid Med	dicalw/ wa	aivers/lim.		Date of L	ast Me	edical E	xam: 05/2002	
	-						-				
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	light Instrument Actual Simulated			Rotorcraft	Glider	Lighter Than Air
Total Time	6417	1242	1811	4072	1000	120	0 3	00		6	
Pilot In Command(PIC)	6112	1240	1775	4050	990	112	_	00			
Instructor	3300	15	750	3800	800	100	0				
Last 90 Days	53	34	45	8							
Last 30 Days Last 24 Hours	3	3	3		+			_			
Seatbelt Used? Yes	Shou	lder Harness	Used? Ves		Toxic	ology Perfo	ormed? No		Ise	econd Pilot? No	
- Coalbon Cood. 100	01100				1.0/					140	
Flight Plan/Itinerary											
Type of Flight Plan Filed: No	one										
Departure Point					Stat	State Airport Iden		fier Departur		rture Time	Time Zone
Same as Accident/Incident Location CO15							1015		MST		
Destination State Airport Identifier											
Same as Accident/Incident Location CO15											
Type of Clearance: None											
Type of Airspace: Class G											
Weather Information											
Source of Briefing: No record of briefing											
Method of Briefing: Unknown											
			FACTUAL	REPORT	- AVIATIO	N					Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA016

Occurrence Date: 11/17/2002

Occurrence Type: Accident

	FTYBOR		000000000000000000000000000000000000000	, o . , p o.	710010011								
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Di	NOF Distance From Accident Site Dir					Direction From Accident Site		
AFF	1055	MST	6572 Ft.	MSL			17 NM 200 Deg.					Mag.	
Sky/Lowes	st Cloud Condition: Few				12	2000 Ft. /	AGL	Condition of Light: Day					
Lowest Ce	illing: Broken		22000 Ft.	AGI	Visibi	lity:	12	<u> </u>					
		5 5											
Temperati	ıre: 16 °C	Dew Point:	-9 °C		Direction:			Density Altitude: 8172 Ft.					
Wind Spee	ed: 6	Gusts:		Weath	ner Condti	ions at Ac	cident S	ite: Visual C	Condi	itions			
Visibility (F	RVR): Ft.	Visibility (R)	VV)	SM	Intensity	of Precip	oitation:						
Restriction	s to Visibility: None	•											
Type of Pr	ecipitation: None												
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,													
Accident	Information												
Accident Information													
Aircraft Da	Aircraft Damage: Substantial Aircraft Fire: None Aircraft Explosion None												
Classificat	on: U.S. Registered/U	J.S. Soil											
- Injury Su	mmary Matrix	Fatal Se	rious Mino	r	None	TOTAL							
First P	ilot				1		1						
Secon	d Pilot												
Studer	t Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin	Attendants												
Other (Crew												
Passer	ngers				1		1						
- TOTAL /	ABOARD -				2		2						
Other (Ground				_								
- GRANI	O TOTAL -				2		2						
		•					•						

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: DEN03LA016

Occurrence Date: 11/17/2002

Occurrence Type: Accident

Δ	dm	inis	trativ	r⊵ Int	f∩rm	ation
$\overline{}$	ulli	บบอ	uauv			alioi

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

Gregory M Zadar Aviation Safety Inspector - Air Carrier / Avionics Denver Flight Standards District Office 26805 East 68th Avenue, Suite 200 Denver, CO 80249